


GM 500 USER ACTIVATED STATION STOP

← OUT

← IN



CONTROLLER

DC TRACK FEED

3

2

1

A

B

6

5

4

C

PUSH BUTTON

FEED TO SWITCHES

16v AC

POWER SUPPLY